

AASHTO Specifications

| AASHTO # | 4" | 3-1/2" | 3" | 2-1/2" | 2" | 1-1/2" | 1" | 3/4" | 1/2" | 3/8" | #4 | #8 | #16 | #50 | #100 |
|----------|------|---------|------|---------|---------|---------|---------|---------|---------|---------|---------|--------|-------|------|--------|
| 1 | 100% | 90-100% | | 25-60% | | 0-15% | | 0-5 | | | | | | | |
| 2 | | | 100% | 90-100% | 35-70% | 0-15% | | 0-5 | | | | | | | |
| 24 | | | 100% | 90-100% | | 25-60% | | 0-10 | 0-5 | | | | | | |
| 3 | | | | 100% | 90-100% | 35-70% | 0-15 | | 0-5 | | | | | | |
| 357 | | | | 100% | 95-100% | | 35-70 | | 10-30% | | 0-5% | | | | |
| 4 | | | | | 100% | 90-100% | 20-65% | 0-15% | | 0-5% | | | | | |
| Area #4 | | | | 100% | 90-100% | 60-90% | 10-30% | | | 0-1% | | | | | |
| 467 | | | | | 100% | 95-100% | | 35-70% | | 10-30% | 0-5% | | | | |
| 5 | | | | | | 100% | 90-100% | 20-55% | 0-10% | 0-5% | | | | | |
| 56 | | | | | | 100% | 90-100% | 40-85% | 10-40% | 0-15% | 0-5% | | | | |
| 57 | | | | | | 100% | 95-100% | | 25-80% | | 0-10% | 0-5% | | | |
| 6 | | | | | | | 100% | 90-100% | 20-55% | 0-15% | 0-5% | | | | |
| 67 | | | | | | | 100% | 90-101% | | 20-55% | 0-10% | 0-5% | | | |
| 68 | | | | | | | 100% | 90-102% | | 30-65% | 5-25% | 0-10% | 0-5% | | |
| 7 | | | | | | | | 100% | 90-100% | 40-70% | 0-15% | 0-5% | | | |
| 78 | | | | | | | | 100% | 90-100% | 40-75% | 5-25% | 0-10% | 0-5% | | |
| 8 | | | | | | | | | 100% | 85-100% | 10-30% | 0-10% | 0-5% | | |
| 89 | | | | | | | | | 100% | 90-100% | 20-55% | 5-30% | 0-10% | 0-5% | |
| 9 | | | | | | | | | | 100% | 85-100% | 10-40% | 0-10% | 0-5% | |
| 10 | | | | | | | | | | 100% | 85-100% | | | | 10-30% |